

NOX-CRETE BioClean Plus Concentrate

Citrus based concrete stripper Bio-Clean Plus is a powerful, water-dilutable stripper with a formulation to deeply penetrate concrete floor and wall surfaces.

The result is safe and effective removal of most surface contaminants. Use it to remove most curing compounds, tilt-up bondbreakers, paints and coatings.

Advantages



Excellent concrete stripping agent

Fast acting formula quickly and effectively removes curing compounds, tilt-up bondbreakers, paints and coatings from concrete floor and wall panels.



Zero tolerance for residue

High solvency and slow drying formulation ensures deep penetration and thorough removal of all coating residue.



Safer and more effective

Green engineered™, 100% biodegradable and non-toxic compound, leaving a pleasant citrus and pine scent after cleaning.

Applications



Use on both new and existing interior or exterior concrete floor and wall surfaces.



Use to remove/strip bondbreaker or curing compound residue, prior to application of other floor or wall treatments, coverings or coatings.



Also used to remove/strip unsightly, scratched or worn out floor paints and coatings.

PRECAUTIONS



Do not apply to composition or resilient tile.



Do not apply to any painted surface, unless the painted surface is to be stripped.



Do not use in the presence of open food stuffs. Protect from accidental splatter and freezing.



Before application



After application

Packaging & Product Codes

Part No.	Size	Pack
NOXBIOCLEAN4	4L	Jug
NOXBIOCLEAN20	20L	Pail

Price

Customer: _____

Contact Name & Number: _____

Recommended Price:

\$ _____



Use Instructions

- Dilute BIO-CLEAN PLUS 1:1 with water for stripping heavy coatings. For removal of lighter coatings, a dilution ratio of 1:3 or 1:4 with water is generally sufficient.
- Uniformly apply by sprayer or through an automatic floor machine at an application rate of 5-7.5m² per litre.
- Allow product to work for 20-30 minutes while aggressively scrubbing the floor

surface with an automatic floor machine equipped with nylon scrub brushes.

- Squeegee the surface clean and rinse thoroughly with water.
- After stripping with BIO-CLEAN PLUS, allow adequate time for the cleaned surface to completely dry before coating or recoating the floor. Generally a minimum of 24-48 hours is recommended.